


PIENAAR ENERGY (PTY) LTD

Solar inverter fault code 039



Overview

Error Code 039 indicates a critical isolation fault in the Sungrow inverter. This fault can affect the system's safety and performance. ABN 76 168 258 679 and is intended as a guideline to assist solar installers for troubleshooting. Please observe. These faults apply to the following sungrow products: In the event of Fault Code 39 being informed through the App, the following corrective measures shall be taken: Low System Insulation Resistance (Code 039) The insulation resistance to ground of the PV module is lower than the standard value. Learn more Is your Sungrow. If your Sungrow inverter is showing a fault or not performing as expected, the display screen or monitoring app may present an error code.

Solar inverter fault code 039




Sungrow Inverter Fault Codes: A Quick Troubleshooting Guide

Even with proper maintenance, Sungrow inverters may occasionally display critical fault codes. Here are step-by-step solutions to resolve some of the most common and significant errors:

[Get Price](#)


TD 202104 All Low PV Insulation Resistance V1.2





The document provides guidelines for troubleshooting Low Insulation Resistance Errors (039 for Grid-Connected and 302 for Hybrid Inverters) in solar installations, indicating potential earth faults in the ...



[Get Price](#)

PRODUCT INFORMATION



-  **BATTERY CAPACITY**
50kWh~500kWh
-  **DC VOLTAGE RANGE**
400V~1000V
-  **DEGREE OF PROTECTION**
IP54
-  **OPERATING TEMPERATURE RANGE**
-10~50°C

Our Sungrow Inverter Troubleshooting Guide

Check the AC breaker and cables, but if they look fine, call a technician. Sungrow error 039 - Low insulation resistance. This usually means a ground fault or moisture somewhere in the PV ...

[Get Price](#)

Sungrow Error Code 039 - Meaning, Causes & Solution

Learn about Sungrow Error Code 039, its meaning, causes, and solutions for isolation faults. oWhat does Error Code 039 indicate? Error Code 039 indicates a critical isolation fault in the Sungrow inverter. ...



[Get Price](#)



Our Sungrow Inverter Troubleshooting Guide


Check the AC breaker and cables, but if they look fine, call a ...

[Get Price](#)

Solar Inverter Error Codes Explained (Fronius, Sungrow, GoodWe)

Solar inverter error codes explained for Fronius, Sungrow, GoodWe and SolarEdge. Learn what each error means, common causes, fixes and when to call your installer.

[Get Price](#)



Fault code 039: Low System Insulation Resistance

This manual is intended for professional technicians who are responsible for



installation, operation, maintenance and troubleshooting of inverters, and users who need to check inverter parameters.

[Get Price](#)

Sungrow Solar Inverter Status Error 039

Is your Sungrow solar inverter beeping and showing a STATUS ERROR 039 message? If so your solar power system isn't working, find out what the ERROR 039 messa



[Get Price](#)



Error 039 / 302 Low PV Insulation Resistance

Low Insulation Resistance Error (039 for Grid-Connected and 302 for Hybrid Inverters) indicates that there could be an Earth Fault in the PV array. There can be a few things causing this issue, hence, ...

[Get Price](#)

Sungrow Inverter Error Codes & Troubleshooting Guide

This page outlines the most common Sungrow inverter error codes, what they

mean, and what you can do about them--whether you own a residential system or a larger commercial setup.

[Get Price](#)



Contact Us

For catalog requests, pricing, or partnerships, please visit:
<https://pienaarshof.co.za>

