

PIENAAR ENERGY (PTY) LTD

Host and base station communication failed



Overview

This section describes some possible station setup and static measurement issues, possible causes, and how to solve them. Trimble recommends that you use the Siteworks or SCS900 software to restart or configure base and rover receivers. The software sets up all radio and receiver operating. If you're experiencing communication issues with your USB data logger, base station, and shuttle, here are a few things to consider: If using Windows - If using a Mac - For either Windows or Mac - . Under certain circumstances the 6320 doesn't establish nor maintain an interface connection between 2020-5BE base station and host computer. DPM scanner loses my connection to the base / base connection gets lost.

Host and base station communication failed



 **LFP 12V 200Ah**

Troubleshooting communication issues with USB data loggers, base

Troubleshooting communication issues with USB data loggers, base stations, and shuttles

[Get Price](#)

CDMA2000 1xEV-DO Base Station Troubleshooting Guide

Use BTS Over-the-Air (OTA) tests to spot-check a transmitters' coverage and signal quality. Use the Direct Connect tests to check transmitter power and when the OTA test results are ambiguous. ...

[Get Price](#)



Solved: Base station communication to cameras constantly f

If you're having problems where your Arlo cameras aren't communicating to the Base Station, try reading this article to see how you can troubleshoot: My Arlo wire-free camera is offline; ...

[Get Price](#)



Getting a "Device Identification Failed" in Base Station

I can control my device in alpha station - i cab toggle relay and with the LEDs go on and off as connected but in base station the device Id fails and I have no connectivity even though the ...

[Get Price](#)



Troubleshooting base station setup and static measurement problems

This section describes some possible station setup and static measurement issues, possible causes, and how to solve them. Trimble recommends that you use the Trimble Access software to restart or ...

[Get Price](#)

Troubleshooting communication

If you are seeing a "communication failed" error message while starting up the on-line instrument session, the following steps should assist you in testing your system and determining the cause of ...

[Get Price](#)



GNSS survey error messages

If the survey still fails to start correctly,

there may be a problem with the IP address or port number in the style, or the base station providing the data may not be operational.



[Get Price](#)

6320 loosing host connection / not connecting to base

6320 Scanner firmware 2.1.0 and 2.1.1 introduced a communications problem and those Firmware versions require transmission of unprotected commands, and moving forward the 6320 base station ...



[Get Price](#)

Contact Us

For catalog requests, pricing, or partnerships, please visit:
<https://pienaarshof.co.za>

